

1. CARACTERÍSTICAS TÉCNICAS / TECHNIAL FEATURES

Extractores para interiores. / **Internal puller**


Tipo pinza de dos piezas. / **Collet type of two parts.**

Fabricadas en material CrVa. / **Made in CrVa.**

Con dos sistemas para la extracción / **With 2 system of extraction:**

Barra de impacto y puente con patas / **Slide hammer and push puller with jaws.**

2. DIMENSIONES DEL EXTRACTOR / PULLER DIMENSIONS



2500 y 2510

2511 a 2518



Ref.	ØA	B	ØD	L	M	Peso Weigth
2500	5-7	11	15	27	M-10x1,5	0,1
2510	8-11	21	15	40	M-10x1,5	0,1
2511	12-25	28	26	50	M-10x1,5	0,1
2512	16-19	35	26	50	M-10x1,5	0,2
2513	20-26	35	34	55	M-10x1,5	0,3
2514	28-34	60	34	60	M-10x1,5	0,4
2515A	35-44	60	35	60	M-10x1,5	0,7
2515	35-44	75	43	75	M-16x2	0,7
2516	45-58	90	43	90	M-16x2	0,9
2517	57-75	110	62	110	M-16x2	2,2
2518	74-100	130	62	130	M-16x2	3,4

■ 3. INSTRUCCIONES DE USO / USER INSTRUCTIONS



1. Asegúrese de que el husillo está perfectamente limpio y engrasado.
2. Compruebe que el eje esté punteado. Si no lo estuviera, colóquelo un protector de punto.
3. Asegúrese que las patas estén perfectamente centradas.
4. Realice la fuerza de extracción girando el husillo. Nunca golpear el husillo.
5. No mantenga el husillo demasiado salido del cuerpo.
6. Utilice todos los equipos de protección individual (EPIs) necesarios

1. Make sure that the spindle is perfectly clean and greased.
2. Check that the axis is dotted. If it is not, place a point protector.
3. Make sure that the jaws are perfectly centered.
4. Apply the extraction force by turning the spindle. Never hit the spindle.
5. Do not keep the spindle too far out of the body.
6. Use all the necessary personal protective equipment (PPE)



1. Introducir la pinza en al agujero.
/ Insert the collet into the hole.

2. Abrir la pinza hasta alcanzar el diámetro de la pieza a extraer.
/ Open the collet until reach the diameter of the part to be extracted.

